Appendix C

Photo Logs – Test Trenches, Soil Borings



Photo 1 Test trench SOC4-TT1.



Photo 2 Test trench SOC4-TT9, debris encountered.

 $\label{eq:point} P:\Delta MN(19)2319B05 \ UMore \ park \ environmental \ WorkFiles\ Phase \ II \ Investigation \ WO#1 \ and \ \#6\ Implementation\ SSI_RI\ Report\ V2.0\ Appendicies\ C \ - \ Photologs\ Test_Trench_Boring_Photolog \ Not \ No$

^{1 of 8} UMP018471



Photo 3 Spoil pile from test trench SOC4-TT9. Debris encountered included concrete, plastic, metal, glass, ash, shingles and tiles.



Photo 4 Test trench SOC4-TT9B, debris encountered.



Photo 5 35-gallon drum containing gypsum wallboard found in test trench SOC4-TT9B.



Photo 6 Test trench SOC4-TT12. Analytical soil sample SOC4-TT12-0.5' was collected from 0.5 feet below ground surface in this test trench.



Photo 7 Test trench SOC5-TT17.



Photo 8 Tar coating on DNT storage bunker 260-H (Bld. 604) and drainage tile removed from the perimeter of the building.



Photo 9 Tar coating and poorly graded gravel layer below the floor slab at DNT storage bunker 260-H (Bld. 604).



Photo 10 Test trench SOC5-TT29 in the former rinsate lagoon. Lagoon liner was observed in this test trench.



Photo 11 Work zone delineation at SOC5-GP6



Photo 12 Stained soils at SOC5-GP8



Photo 13 Temporary well installation at SOC4-GP1



Photo 14 Pesticide sampling borings at SOC5-GP13, locations A through D



Photo 15 Drilling on the DNT storage bunker berm at SOC5-GP21



Photo 16 Groundwater sampling at SOC5-GP3