



9/20/06: view facing northwest.



9/20/06: view facing west.



9/6/06: concrete footing in test trench 1, located in the southeast corner of the building.



9/6/06: test trench 1 facing west.

Building 101B, East Guncotton/Nitrocellulose Production Area (A, B,C Lines)



9/20/06: view facing south of concrete remnant of the building.



9/20/06: view facing southeast of concrete remnant and footing locations hidden by trees.



9/6/06: concrete footing in test trench 8.



9/13/06: facing north, location of concrete sample 10 on concrete footing piece.



9/20/06: view facing north of concrete building pad location framed out by bushes.



9/20/06: view facing southeast of concrete building pad hidden by foliage.



9/6/06: clay pipe discovered in test trench 2 located along the west central part of western building wall.



9/6/06: dry well discovered in test trench 2 located a few feet south of the clay pipe that was discovered.



9/20/06: view facing east of building pad.



9/20/06: view facing west of building pad hidden by trees.



9/6/06: test trench 4 located on the north side of the building.



9/6/06: concrete footing with wooden pole in test trench 4.

Building 105B, East Guncotton/Nitrocellulose Production Area (A, B,C Lines)



9/20/06: view facing east of concrete building pad.



9/20/06: view facing north of concrete building pad.



9/6/06: concrete footing and clay pipe in test trench 5 located on south side of the building.



9/6/06: concrete footing along test trench 5 along south side of the building.



9/20/06: view facing northeast of pillars standing on the concrete building pad.



9/20/06: view facing southeast of pillars in the trees standing on the concrete building pad.



9/6/06: test trench 9 located in the south western portion of the south building wall near a save-all.



9/6/06: test trench 10 located in the south eastern portion of the south building wall.



9/20/06: view facing east of concrete building pad.



9/20/06: view facing northeast of concrete building pad.



9/6/06: test trench 11 located along the central portion of the west building wall.



9/6/06: clay pipe discovered in test trench 11.



9/21/06: view facing east of concrete building pad.



9/21/06: view facing south of concrete building pad.



9/7/06: dry well discovered in test trench 18 located on the north side of the building.



9/7/06: building footing along test trench 18 located on the north side of the building.



9/21/06: view facing northeast of concrete supports on the concrete building pad.



9/21/06: view facing south of concrete supports on the concrete building pad.



9/6/06: building footing along test trench 14 located along the southern area of the west building wall.



9/6/06: cast iron pipe discovered in test trench 14 located along the southern area of the west building wall.

Building 112B, East Guncotton/Nitrocellulose Production Area (A, B,C Lines)



9/21/06: view facing east of concrete building pad and concrete supports.



9/21/06: view facing west of concrete supports on building pad. Pad hidden by foliage.



9/7/06: building footing along test trench 17 located along the southern portion of the west building wall.



9/7/06: dry well discovered in test trench 17 in the southwest corner.

Building 113B, East Guncotton/Nitrocellulose Production Area (A, B,C Lines)



9/21/06: view facing east of concrete building remnant.



9/21/06: view facing south of concrete building remnant.



9/6/06: three cast iron pipes discovered in test trench 13 located on the east side of the building.



9/6/06: clay pipe discovered in test trench 13 located on the east side of the building.

Building 120B-1, East Guncotton/Nitrocellulose Production Area (A, B,C Lines)



9/21/06: view facing north of concrete building pad hidden by foliage.



9/21/06: view facing northeast of concrete building pad.



9/7/06: test trench 20 located at the northwest corner of the building.



9/14/06: location of concrete sample 26.



9/21/06: view facing north of building.



9/21/06: view facing west of building.



9/6/06: building footing along test trench 12 located on the east side of the building.



9/6/06: clay pipe discovered in test trench 12 located on the east side of the building.

Building 501B East Guncotton/Nitrocellulose Production Area (A, B,C Lines)



Building 706J, view facing south of concrete building pad.



Building 706J, view facing southeast of concrete building pad hidden by trees.



Building 706J, pipes discovered in test trench 15 located on the north side of the building.



Building 706J, location of concrete sample 12 on the concrete building pad.

Building 706J East Guncotton/Nitrocellulose Production Area (A, B,C Lines)



Building 722B, view facing east of the concrete building pad.



Building 722B, view facing northwest of the concrete building pad.



Building 722B, building footing along test trench 6 located on the southeast corner of the building.



Building 722B, dry well discovered in test trench 6 located on the southeast corner of the building.

Building 722B East Guncotton/Nitrocellulose Production Area (A, B,C Lines)