



9/25/06: view facing north of concrete building pad.



9/25/06: view facing south of concrete building remnants.



9/11/06: pipe discovered and concrete footing along test trench 63 located on the southeast corner of the building.



9/11/06: possible ACM red mastic on concrete building pad.



9/25/06: view facing north of raised concrete building pad.



9/25/06: view facing northeast of raised concrete building pad.



9/11/06: red mastic on soil at test trench 65 located on the south side of the building. Red staining from the flooring mastic on footing wall.



9/11/06: building footing and dry well at test trench 65 located on the south side of the building.



9/25/06: view facing north of concrete building pad hidden in the trees.



9/25/06: view facing east of concrete building pad hidden in the trees.



9/8/06: building footing along test trench 44 located along the west building wall.



9/18/06: location of concrete sample 59 on footing edge.

## Building 235A, East Powder Manufacturing



9/25/06: view facing south of concrete building remnants.



9/25/06: view facing west of concrete building remnants.



9/8/06: dry well discovered in test trench 43 located on the north side of the building.



9/18/06: possible ACM black material and concrete sample 62 on concrete building pad.



9/25/06: view facing northeast of the raised concrete building pad.



9/25/06: view facing northwest of the raised concrete building pad.



9/12/06: building footing and pipe along test trench 72 located on the southeast corner of the building.



9/18/06: possible ACM red mastic and concrete sample 58 on building pad.



9/25/06: view facing east of concrete building pad.



9/25/06: view facing west of raised concrete building pad.



9/12/06: building footing along test trench 71 located on the east side of the building.



9/15/06 location of concrete sample 56 (working on) and 57 (close flag) on the concrete building pads.

## Building 238B, East Powder Manufacturing



9/25/06: view facing north of raised concrete building pad.



9/25/06: view facing west of raised concrete building pad.



9/12/06: building footing along test trench 70 with view of an overflow drain located on the south side of the building.



9/12/06: darker stained soil below the overflow drain in test trench 70 located on the south side of the building.



9/25/06: view facing east of raised concrete building pad.



9/25/06: view facing west of raised concrete building pad



9/11/06: building footing along test trench 67 with red staining from the red mastic on building slab located on the south side of the building.



9/11/06: dry well discovered in test trench 68 located just east of the east building wall..

### Building 240B, East Powder Manufacturing