

Appendix C

Photo Logs – Test Trenches, Soil Borings



Photo 1 SOC2-TT5 Overview.



Photo 2 SOC2-TT5 Sidewall



Photo 3 SOC3-TT16 Sidewall



Photo 4 SOC8-TT5 Sidewall



Photo 5 SOC7-TT4 Sidewall



Photo 6 Former Lagoon Liner at SOC3-TT2



Photo 7 Fill at SOC3-TT10



Photo 8 Debris at SOC3-TT9. Debris encountered during excavation included concrete, metal, and ceramic.



Photo 9 Setup at SOC6-GP4




Photo 10 St Peter Sandstone at SOC6-GP6



Photo 11 Diamicton till at SOC6-GP6



Photo 12 Outwash at SOC3-GP3



Photo 13 Diamictite till at SOC3-GP3



Photo 14 Setup at SOC3-GP2



Photo 15 Lacustrine deposits at SOC1-GP1



Photo 16 1" PVC screen and drive point



Photo 17 Temporary well at SOC3-GP2