

APPENDIX M
PROPERTY VISIT PHOTOGRAPHS
18 – 22 July 2005

Photograph 01: Standing at Bottom of Waste Disposal Ditch South of 170th Looking to the Northwest

Photograph 02: Walking to the Southwest Along Bottom of Waste Disposal Ditch South of 170th

Photograph 03: Looking to the Southwest at the Former Primary Settling Pond - Now Bean Field

Photograph 04: Former Shipping/Storage Bldgs Looking Southeast

Photograph 05: Former Shipping/Storage Bldgs Looking East

Photograph 06: Former Shipping/Storage Bldgs Close-up of Soil

Photograph 07: Standing at Bottom of 154th Street Disturbed Area Looking to the Southwest

Photograph 08: Example Rebar Protruding in 154th Street Disturbed Area

Photograph 09: 155th Street Disturbed Area Looking Northeast

Photograph 10: Disturbed Area South of 155th Street - Possible Borrow

Photograph 11: Drainage Ditch South of DNT Bunkers Looking to the Northeast



Photograph 01: Standing at Bottom of Waste Disposal Ditch South of 170th Looking to the Northwest



Photograph 02: Walking to the Southwest Along Bottom of Waste Disposal Ditch South of 170th



Photograph 03: Looking to the Southwest at the Former Primary Settling Pond - Now Bean Field



Photograph 04: Former Shipping/Storage Bldgs Looking Southeast



Photograph 05: Former Shipping/Storage Bldgs Looking East



Photograph 06: Former Shipping/Storage Bldgs Close-up of Soil



Photograph 07: Standing at Bottom of 154th Street Disturbed Area Looking to the Northeast



Photograph 08: Example Rebar Protruding in 154th Street Disturbed Area



Photograph 09: 154th Street Disturbed Area Looking Southwest



Photograph 10: Disturbed Area South of 154th Street - Possible Borrow



Photograph 11: Drainage Ditch South of DNT Bunkers Looking to the Northwest

