



9/23/06: view facing north of the concrete building pad.



9/23/06: view facing southwest of the concrete building pad.



9/7/06: concrete footing along test trench 31 located along south-east corner of the building.



9/7/06: location of concrete sample 35 on the concrete building pad.

Building 207B East Solvent Area



9/23/06: view facing east of the concrete building pad.



9/23/06: view facing northeast of the concrete building pad.



9/23/06: concrete footing along test trench 46 along south side of building.



9/23/06: location of test trench 47 along the north side of the building.



9/23/06: view facing north of the concrete building pad.



9/23/06: view facing northeast of the concrete building pad.



9/7/06: building footing along test trench 36 on the southwest corner of the building.



9/7/06: location of concrete sample 37 located on the edge of the building pad. Red mastic on top of concrete building slab.

Building 209A East Solvent Area



9/23/06: view facing northeast of concrete building pad.



9/23/06: view facing northwest of foliage debris on top of the concrete building pad.



9/7/06: vertical pipe discovered in test trench 28 located along the western area of the southern building wall..



9/7/06: building footing along test trench 29 located along southern wall of the building and a steel pipe.

Building 226A East Solvent Area



9/23/06: view facing east of the concrete building pad.



9/23/06: view facing north of concrete building pad.



9/7/06: building footing along test trench 21 located on northeast corner of the building.



9/7/06: test trench 22 located along west building wall.

Building 202C East Solvent Area




9/23/06: view facing south of concrete drive and test trench locations.



9/23/06: view facing southwest of concrete drive and test trench locations.



9/14/06: test trench 27 located just west of the concrete drive.



9/14/06: location of concrete sample 32 on concrete drive.



9/23/06: view facing northwest of concrete building remnants.



9/23/06: view facing south of concrete building remnants.



9/8/06: building footing along test trench 38 located on the north-east corner of the building.



9/8/06: piece of wood box drain in test trench 39 located just east of the east building wall.

Building 205A East Solvent Area



9/24/06: view facing northeast of concrete building pad hidden by trees.



9/24/06: view facing west of concrete building pad.



9/7/06: dry well discovered in test trench 25 located on southwest corner of the building.



9/14/06: concrete sample 31 on the concrete building pad.



9/24/06: view facing northeast of building remnant.



9/24/06 view facing southeast of building remnant.



9/7/06: building footing along test trench 23 located along the central portion of the west building wall.



9/7/06: clay pipe discovered in test trench 24 located of the north-east corner of the building.

Building 208C East Solvent Area



9/24/06: view facing south of building remnant.



9/24/06: view facing southwest of building remnant.



9/7/06: building footing along test trench 30 located along the central portion of the southern building well.



9/7/06 possible ACM on the surface at test trench 30.

Building 234H East Solvent Area



9/24/06: view facing north of a portion of the building remnant.



9/24/06: view facing southeast of a portion of the building remnant.



9/7/06: building footing along test trench 33 located east of the tank saddles.



9/7/06: vertical clay pipes discovered in test trench 34 located east of TT-33 through former building slab.

Building 251B East Solvent Area



9/25/06: view facing north of building remnant.



9/25/06: view facing southwest of building remnant.



9/8/06: test trench 40 located on southeast corner of building.



9/8/06: concrete sample 48 located on southwest area of building.

Building 214C-13 East Solvent Area



9/24/06: view facing northwest of concrete building pad.



9/24/06: view facing east of concrete building pad.



9/7/06: building footing along test trench 37 located on the north-east corner of the building (building number in photo is wrong).



9/7/06: dry well discovered in test trench 37 located on the north-east corner of the building (building number in photo is wrong).

Building 233A East Solvent Area



9/25/06: view facing south of concrete building remnants.



9/25/06: view facing east of concrete building remnants.



9/8/06: building footing along test trench 41 located on the northwest corner of the building.



9/8/06: dry well material in test trench 42 (test trench number in photo wrong) located on northeast corner of the building.

Building 269B East Solvent Area