



# Test Trench Log

Test Trench No.: TT-43-236B

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/8/06

Date Completed: 9/8/06

Elevation (ft): 0

Total Depth (ft): 6

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-43-236B (0-1')		0.0	Sand, trace organics, fine to medium, poorly sorted, loose, dark brown		Topsoil
-2	2			0.0			Near possible dry well and horizontal cast iron pipe
-4	4	TT-43-236B (1-6')		0.0	Sand, medium to coarse, poorly sorted, loose, moist, brown		
-6	6				End of Test Trench		Depth to top of footing 2.5'
-8	8						
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-44-235A

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/8/06

Date Completed: 9/8/06

Elevation (ft): 0

Total Depth (ft): 10

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-44-235A (0-1')		0.0	Sand, fine to medium, poorly sorted, loose, moist, dark brown		Topsoil
-2	2			0.0			Near cast iron pipe (3.5' deep)
-4	4						
-6	6	TT-44-235A (1-10')		0.0	Sand, fine to medium, poorly sorted, loose, moist, brown		
-8	8						
-10	10				End of Test Trench		
-12	12						Depth to top of footing 10'
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-63-202C

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/11/06

Date Completed: 9/11/06

Elevation (ft): 0

Total Depth (ft): 10

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-63-202C (0-1')		0.0	Sand, fine to medium, poorly sorted, loose, moist, dark brown		Topsoil
-2	2			0.0			Depth to top of building 2'
-4	4			0.0			
-6	6	TT-63-202C (1-10')		0.0	Sand, medium to coarse, poorly sorted, loose, moist, brown		Horizontal pipe at 6'
-8	8						Depth to top of sump 6'
-10	10				End of Test Trench		
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-64-220C

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/11/06

Date Completed: 9/11/06

Elevation (ft): 0

Total Depth (ft): 5

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-64-220C (0-1')		0.0	Sand, fine to medium, poorly sorted, loose, moist, dark brown		Topsoil
-2	2			0.0			
-4	4	TT-64-220C (1-5')		0.0	Sand, medium to coarse, poorly sorted, loose, moist, brown		Depth to top of footing 2'
-6	6				End of Test Trench		
-8	8						
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-65-222A

Project: UMore Park

Contractor/Crew: Veit Speciality








Date Started: 9/11/06

Date Completed: 9/11/06

Elevation (ft): 0

Total Depth (ft): 12

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-65-222A (0-6")		0.0	Sand, red material from building in soil		
-2	2			0.0			Near possible dry well
-4	4			0.0			Metal pipe at 3'
-6	6	TT-65-222A (6"-12")		0.0	Sand, medium to coarse, poorly sorted, loose, moist, brown		Depth to top of footing 3'
-8	8						
-10	10						
-12	12				End of Test Trench		
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-66-222A

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/11/06

Date Completed: 9/11/06

Elevation (ft): 0

Total Depth (ft): 1

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-66-222A (0-1')		0.0	Sand and gravel		Topsoil
					End of Test Trench		
-2	2						
-4	4						
-6	6						Depth to top of footing 3'
-8	8						
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-67-240B

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/11/06

Date Completed: 9/11/06

Elevation (ft): 0

Total Depth (ft): 6

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-67-240B (0-6")		0.0	Sand, fine to medium, poorly sorted, loose, moist, brown, red along building		Depth to top of footing 4'
-2	2	TT-67-240B (6"-4')		0.0	Silty sand, fine to medium, poorly sorted, loose, moist, brown		
-4	4	TT-67-240B (4-6')		0.0	Sand, medium to coarse, poorly sorted, loose, moist, brown		
-6	6				End of Test Trench		
-8	8						
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-68-240B

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/11/06

Date Completed: 9/11/06

Elevation (ft): 0

Total Depth (ft): 8

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-68-240B (0-1')		0.0	Sand, trace organics, fine to medium, poorly sorted, loose, moist, dark brown		Topsoil
-2	2	TT-68-240B (1-3')		0.0	Silty sand, fine to medium, poorly sorted, loose, moist, brown		
-4	4						
-6	6	TT-68-240B (3-8')		0.0	Sand, medium to coarse, poorly sorted, loose, moist, brown		Depth to top of footing 4'
-8	8				End of Test Trench		
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						





# Test Trench Log

Test Trench No.: TT-70-239A

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/12/06

Date Completed: 9/12/06

Elevation (ft): 0

Total Depth (ft): 9

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-70-239A (0-1')		0.0	Sand, trace organic, fine to medium, poorly sorted, loose, moist, dark brown		Topsoil
-2	2	TT-70-239A (1-3')		0.0	Silty sand, fine to coarse, poorly sorted, dense, moist, brown		
-4	4	TT-70-239A (3-4')		0.0			
-4	4	TT-70-239A (4-5')		0.0			
-6	6	TT-70-239A (5-9')		0.0			
-8	8				End of Test Trench		
-10	10						Depth to top of footing 8'
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-71-238B

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/12/06

Date Completed: 9/12/06

Elevation (ft): 0

Total Depth (ft): 5

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-71-238B (0-1')		0.0	Silty sand, fine to medium, poorly sorted, medium dense, moist, dark brown		Topsoil
-2	2	TT-71-238B (1-3')		0.0	Silty sand, fine to medium, poorly sorted, loose, moist, brown		
-4	4	TT-71-238B (3-5')		0.0	Sand, medium to coarse, poorly sorted, loose, moist, brown		
					End of Test Trench		
-6	6						Depth to top of footing 4'
-8	8						
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-72-237K

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/12/06

Date Completed: 9/12/06

Elevation (ft): 0

Total Depth (ft): 8

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-72-237K (0-1')		0.0	Sand, fine to medium, poorly sorted, loose, moist, dark brown		Topsoil
-2	2	TT-72-237K (1-3')		0.0	Silty sand, fine to medium, poorly sorted, medium dense, brown		
-4	4	TT-72-237K (3-5')		0.0	Sand, medium to coarse, poorly sorted, loose, moist, brown		Depth to top of footing 2'
-6	6	TT-72-237K (5-7')		0.0	Sand, medium to very coarse, poorly sorted, loose, moist, brown		
					End of Test Trench		
-8	8						
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						