



9/25/06: view facing southwest of the concrete building pad hidden on top of the hill and test trench 69 location.



9/25/06: view facing west of the concrete building pad.



9/12/06: gray material near surface at test trench 69 located on the central portion of the north building wall.



9/12/06 building footing along test trench 69 located on the central portion of the north building wall.

Building 224A, Powder Testing-North, South, and West



9/25/06: view facing south of building remnant.



9/25/06: view facing east of building remnant.



9/8/06: building footing along test trench 45 (building number in photo is wrong) located on the northwest corner of the building.



9/8/06: dry well discovered in test trench 45 located on the northwest corner of the building.

Building 228C, Powder Testing-North, South, and West