



Test Trench Log

Test Trench No.: TT-45-228C

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/8/06

Date Completed: 9/8/06

Elevation (ft): 0

Total Depth (ft): 7

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-45-228C (0-1')		0.0	Sand, fine to medium, poorly sorted, loose, moist, dark brown		
-2	2			0.0			Topsoil
-4	4	TT-45-228C (1-7')		0.0	Sand, medium to coarse, poorly sorted, loose, moist, brown		Near clay pipe at 5'
-6	6						Depth to top of footing 4'
-8	8				End of Test Trench		
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



Test Trench Log

Test Trench No.: TT-69-224A

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/12/06

Date Completed: 9/12/06

Elevation (ft): 0

Total Depth (ft): 5

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-69-224A (0-1')		0.0	Sand, fine to medium, poorly sorted, loose, moist, brown, trace organics		0-2" gray material Gray powder material at surface
-2	2	TT-69-224A (1-3')		0.0	Silty sand, fine to medium, poorly sorted, loose, moist, brown		
-4	4	TT-69-224A (3-5')		0.0	Sand, medium to coarse, poorly sorted, loose, moist, brown		
-6	6				End of Test Trench		Depth to top of footing 4'
-8	8						
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						