



9/23/06: view facing northeast of the concrete petroleum storage area.



9/23/06: view facing southeast.



9/8/06: building footing along test trench 49 located along the central portion of the west building wall.



9/8/06: concrete chase for petroleum supply pipes in test trench 49 located along the central portion of the west building wall.



9/23/06: view facing north.



9/23/06: view facing southwest.



9/8/06: orange stained soil along ash trench in test trench 48 located in the south central portion of the west building wall.



9/8/06: orange stained soil in test trench 48 located in the south central portion of the west building wall.