



# Test Trench Log

Test Trench No.: TT-57-726A

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/11/06

Date Completed: 9/11/06

Elevation (ft): 0

Total Depth (ft): 7

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-57-726A (0'-6")		0.0	Sand, fine to medium, poorly sorted, loose, moist, dark brown		Topsoil
-2	2			0.0			
-4	4	TT-57-726A (6"-7")		0.0	Sand, trace gravel, medium to coarse, poorly sorted, loose, moist, brown		Depth to top of footing 2.5'
-6	6						
-8	8				End of Test Trench		
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-58-726A

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/11/06

Date Completed: 9/11/06

Elevation (ft): 0

Total Depth (ft): 5

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-58-726A (0-1')		0.0	Sand, fine to medium, poorly sorted, loose, moist, dark brown		Topsoil
-2	2			0.0			
		TT-58-726A (1-5')			Sand, fine to medium, poorly sorted, loose, moist, brown		
-4	4			0.0			
					End of Test Trench		Depth to top of footing 2.5'
-6	6						
-8	8						
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-59-717A

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/11/06

Date Completed: 9/11/06

Elevation (ft): 0

Total Depth (ft): 3

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-59-717A (0-3')		0.0	Silty sand, fine to medium, poorly sorted, loose, moist, brown		2" Class V
-2	2						Lead pipe in NW corner of footings
-4	4				End of Test Trench		Depth to top of footing 2.5'
-6	6						
-8	8						
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-60-716B

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/11/06

Date Completed: 9/11/06

Elevation (ft): 0

Total Depth (ft): 6

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-60-716B (0-1')		0.0	Sand, trace organics, fine to medium, poorly sorted, loose, moist, dark brown		Topsoil
-2	2			0.0			
-4	4	TT-60-716B (1-6')		0.0	Sand, medium to coarse, poorly sorted, loose, moist, brown		
-6	6				End of Test Trench		
-8	8						Depth to top of footing 6'
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-61-716A

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/11/06

Date Completed: 9/11/06

Elevation (ft): 0

Total Depth (ft): 6

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	T-61-716A (0-1.5')		0.0	Sand, fine to medium, poorly sorted, loose, moist, black to dark brown, trace organics		Topsoil
-2	2			0.0			
-4	4	T-61-716A (1.5-6')			Sand, medium to coarse, poorly sorted, loose, moist, brown		
-6	6				End of Test Trench		
-8	8						Depth to top of footing 5'
-10	10						
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						



# Test Trench Log

Test Trench No.: TT-62-716A

Project: UMore Park

Contractor/Crew: Veit Speciality

Date Started: 9/11/06

Date Completed: 9/11/06

Elevation (ft): 0

Total Depth (ft): 8

Depth to Water (ft): ---

Elev. (ft)	Depth (ft)	Sample	Rec. (ft)	PID (ppm)	Description	Profile	Remarks
0	0	TT-62-716A (0-1')		0.0	Silty sand, fine to medium, poorly sorted, loose, moist, brown		
-2	2	TT-62-716A (1-3')		0.0			Black on east end
-4	4				Sand, medium to coarse, poorly sorted, loose, moist, brown		
-6	6	TT-62-716A (3-8')		0.0			Depth to top of footing 5'
-8	8				End of Test Trench		Sanitary line at 8'
-10	10						Silty sand fill around the sanitary
-12	12						
-14	14						
-16	16						
-18	18						
-20	20						
-22	22						
-24	24						
-26	26						
-28	28						
-30	30						